



Title:	Firmware update for GP58-CR		
Model:	GP58-CR		
Control Number:	F AE_2022010701	Date:	2022/01/07

Technical announcement:



Dear Valuable Customers:

ICT would like to inform our valuable customers below information.

- 1) In order to prevent GP58-CR date/setting issue, firmware version before (includes) **“GP0XXXXMQ(98DA)”** must update it to the latest firmware version **“GP0XXXXN0(2686)”**.
(Please contact ICT local distributors/branches to get the latest firmware & GP58-CR PC tool.)

***The firmware label is showing on CPU board which located in the bottom of GP58-CR, or use GP58-CR PC tool to read out the unit firmware. If your GP-58CR is already experiencing a date/time issue, please perform firmware and tool update using the latest version, regardless of your installed version.

- I) Firmware version label is under the transparent cover
- II) Firmware version read out by GP58-CR PC tool



- 2) After firmware updated, please use the latest GP58-CR PC tool (as link as below) to check and set again the format layout & other relative settings into GP58-CR, to ensure the settings are correct.

(Please contact ICT local distributors/branches to get the latest firmware & GP58-CR PC tool.)

Note: If you don't have a setting data (*.g58), you may use GP58-CR PC tool in order to executive a setting data (*.g58) to copy the setting to the rest of GP58-CR(s).